
PROSPECT ISLAND RESTORATION



Prospect Island






Prospect Island

- Historically farmed
- Part of Yolo Bypass
- Bought by USBR in 1994 for NDNWR
- 2000 Congress fails to authorize NDNWR
- X 2007 breaches
- 2009 Federal Govt. makes available via PBC process
- Northern 3/4 of the island acquired by DWR in 2010



Current Planning Activities

Screening Criteria and Thresholds Select 5 Screening-(completed) **Alternatives** Level **Broad Suite of Initial** Modeling to Advance (completed) Restoration (in progress) **Alternatives** (completed) Restoration objectives CEQA Site conditions and setting Permits (opportunities and constraints) Construction Outcomes hypotheses (future) Supporting future restorations



Existing Topography

- Extensive deeper acreage at Liberty vs. Prospect
- Liberty deep scour hole at main breach, second scour hole at secondary breach; anticipate at Prospect
- Liberty has extensive perimeter connectivity through eroded levee; maintain or abandon Prospect levees?
- Liberty has extensive unvegetated areas within suitable emergent vegetation elevation. Promote emergent veg at Prospect


Conceptual Alternatives Selected for Modeling

- 30 restoration alternatives formulated to represent <u>broad range</u> of ecological outcomes
- 15 chosen for screening-level modeling and assessment based on attributes anticipated to result in <u>broad range</u> of outcomes

Key approach: maximize differences across selected alternatives to assess greatest contrasts

Design Features Key

- Breaches
- Overflow weir
- Primary channels
- Secondary branch channels
- Connecting channels depending on selected breaches
- DWR and Port properties
- Adjacent property access



DRERIP

(Delta Regional Ecosystem Restoration Implementation Plan)

- Panel of experts
- 2-day workshop evaluating 15 alternatives
- Generate a report with 5 recommended alternatives

Current Issues

- DWR access
- Property owner easements
- Seepage
- Vandalism
- Illegal hunting



Interim Land Management

- Attempted RD resurrection
- Levee clearing
- Inspection
- Repair



Prospect Island Miner Slough Levee Inspection Report





U.S. Department of the Interior Bureau of Reclamation Mid-Pacific Region

Station 95+65 – Sloughing on levee crest



USBR Prospect Island Miner Slough Levee Inspection Report - Feb 2008

Special Thanks To:

- Dennis McEwan
- Stuart Siegel
- Gina Benigno
- Ling Chu
- Pam Lindholm
- Laura Flournoy

